

### MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY **BREATH ALCOHOL PROGRAM**

## **DATAMASTER MAINTENANCE REPORT**

REPORT #6

									1127 0111
Complete this report at the Complete this report whene Retain the original and sen-	ver the instrun	nent is servic	ed or repair	ed and v	zi ti nevenedy	placed into se	5 days). rvice.		
DATAMASTER SN 204142 Inv# 127252	Missouri Sta	•				DATE OF INSPEC 02/04/2013			
LOCATION OF INSTRUMENT (STREET	AND CITY)					TIME OF INSPECT			
Washington County Sheriff's Office					12:53 pm actory or if operating within established limits. (Write in observed values				
where determined.) Unmark	in the box by ea ced items must	ach item if fou be corrected	ind to be sa I before usi	tisfactory ng instru	or if operatin nent.	g within establi	shed limit	s. (Write in obsei	rved válue
DIAGNOSTIC CHECK	(PRINTOUT AT	TTACHED)		DATI	E AND TIME	(from printout)	02/04/20	13 12:53	
☑ COMPUTER				Ø	ETECTOR				
☑ PROGRAM				ØF	ILTERS				
HEATERS SAMPLE	CHAMBER _		<u>49</u> ℃	Ø	UARTZ STAN	NDARD			
☑ FLOW DETECTOR					☑ CALIBRATION				
PUMP HIGH SPEED	)			<b>☑</b> PI	RINTER	······	-		
INDICATOR LIGHTS								70/10/	
SIMULATOR SOLUTION	N SUPPLIER <u>F</u>	RepCo Mari	eting Inc.		LOT#_1	2002	EXP. C	OATE 08/29/20	14
SIMULATOR TEMP (34)	°C ± 0.2°C)	34.15	°C S	SIMULAT	OR SN	G11081	EXP. [	OATE 04/03/20	13
ZI CALIBRATION CHECK -	ONLY ONE	STANDARD	IS TO BE II	ISEN DE	D MAINTEN	ANCE BEROB			
Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)									
0.100% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE 0.080% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE 0.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE									
rest 1 <b>≠</b> ,098		TEST 2 🖝				TEST 9 🗢 ,1	00		
PERFORM R.F.I. TEST (I		(ACHED)			<b>1</b>				··-
ndicate the number of Do not include self-a	BREATH TES DMINISTERED	STS IN THE TESTS)	FOLLOWIN	IG RANG	ES SINCE T	HE LAST MA	NTENAN	CE REPORT:	
REFUSALS 0 (004)	0	(.0509)	0	(.1014)	0	(.15-,19)	3	OVER .19	0
IST ANY NEW PARTS AND DESCRIBE AT	IY ALTERATION OR I	HODIFICATION TH	AT WAS MADE	O RESTORI	THE INSTRUMEN	T TO OPERATE SATI	<b>OFACTORILY</b>	AND WITHIN ESTABLI	SHED LIMITS
This instrument is operating satisfactorily.									
ISPECTING OFFICER									
TPA B.M. Beach #254					Tpr B. M. Beard #254				
PETIPERMIT NUMBER/EXPIRATION CA 20137	06/12/20	)14			TELEPHONE NUM -006 (636)				
Breath Alcohol Program, MO Department of Health and Senior Services, Southeast District Office 2875 James Blvd. Popler Bluff MO 63901									
Poplar Bluff, MO 63901									

### REPCO MARKETING INC.

9101488 STONYSTOOK IRIVE RALESCH, N.C. 27604 919-6765480

## CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc. LOT NUMBER: 12002

EXPIRATION DATE: August 29, 2014 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number 12002 of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain \_\_\_\_\_\_\_\_ gms/dl +/-.003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interferring substance.

This solution will produce a vapor alcohol value of \_\_100\_\_+/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is <u>August 30, 2012</u>

The expiration date for this lot number is <u>August 29, 2014</u>

at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President RepCo Marketing, Inc.

Form RM 02

# **BAC DataMaster**Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC USTAMESTER SERIAL NUMBER 204142 02/04/13 12:53

--- DIREMOSTIC CHECK ---

COMPUTAKE

ÇKAY

PK10888: (04-97-2909):

CKSY

HERTERS

SAMPLI DHAMBER:

49⊂

FLOW GETECTOR:

ŬKAY.

#UMP

HICK SPEEDS

OKAY

DETECTORS

YRXQ

FILTERSA

9KAY

SUPATE STANDARD:

ÜKÄY

CALIBRATION:

OKINY.

PRINTER TEST

(\*#\$\&(\)\*\*,-./8123456789:;<=>?@ABCDEFG +
AIUKLMNOPQRSYUVWXYZINIO\_\abcdefghipklmno
pgrsvevwxgz(!)\*\*

**BAC DataMaster** Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204142 02/04/13

TESTING OFFICER:

BERRUBUM

OFFICER 1.D.: 254

PERMIT HUMBER: 826137

EXPIRATION DATE: 96/12/14

MISCELLANEOUS DATA:

--- SUPERVISOR MODE ---

MLANK TEST	, ହୃତ୍ତ	18:57
INTERNAL STANDARD	VERIFIED	12157
EXTERNAL STANDARD	<b>,</b> %9\$	12:57
DLANK TEST	. 233	:2:58
EXTERNAL STANDARD	. 297	(台:58)
BLANK TESY	, ពុភ្ធធ្ន	12:39
EXTERNAL STANDARD	.190	13:30
BLANK TEST	, 3 <u>5</u> 55	13/26

n = 3 | Sim, = .: | AVB. = .899

perator Signature TPK B, M. BROWN

Operator Signature TAR BM Belsel

# BAC DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204142 02/04/13

ARREST TIME: 18:30
SUBJECT NAME:

RF/TEST

DUB: 89/09/99 SEX: W.
STOTE/D.L.: MO/XX
ARRESTING OFFICER:
BEARD/B/M
OFFICER I.D.: 254
TESTING OFFICER:
SAME
OFFICER I.D.:
PERMIT NUMBER: 280137
EXPIRATION DATE: 86/12/14
MISCELLANEOUS DATA:

#### --- BREATH AMALYSIS ---

BLANK TEST INTERNAL STANDARD .000 19:04

VERIFIED 13:04

- RADIO INTERFERENCE

Operator Signature TRR By, Seas

# State of Missouri DEPARTMENT OF HEALTH



# PERMIT TYPE II



#### **BRYAN M BEARD**

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

#### **DATAMASTER**

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

06/12/2012

Number 220137

Expires 06/12/2014

MO 580-0771 (7-85)

Director of State Public Health Laboratory

Director, Department of Health

Lab. 4 (A7-88)